

USER`S MANUAL

MODEL NO.DH-9058A

DIGITALTHERMO-HYGROMETER

MANUFACTURED BY:SIKARLAN LIMITED

MAIN FEATURES

- 1.Slim compact design
- 2.Measures indoor temperature& humidity
- 3.°C/ °F selectable
4. Regulate the humidity function

OPERATION RANGE

Temperature range:

0°C—50°C/32°F —122°F with01°C/°F

Resolution Humidity Range:

Humidity accuracy+/-2% at 65% to 75%

START-UP

The unit will start functioning automatically once the battery insulating tape is pulled off.

°C/ °F SWITCH

Selects between Celsius(°C) or Fahrenheit(°F) temperature unit display.

+/- SLIDE SWITCH

Slide switch to increase or decrease the humidity.

CAUTION-DO NOT apply the unit to water, AC power or extreme weather conditions

The unit should be operated within

0°C—50 °C, 20%— 99%

-IF the humidity area of the display shows “-” ,if means the measured temperature is lower than 0°C or higher than 60 °C,or the measured humidity is lower than20%.But the unit is not recommend to use former cases with extreme high or low temperature.When the ambient comditionsresume normal operation range,the humidity area of the display will show the correct humidity accordingly.

DO NOT intend to dismantle the unit's internal components


DO NOT insert any used battery not any other battery type except LR43.

Dispose the used batteries properly with environmental care as they are harmful.

BATTERY REPLACEMENT

Slide open the built-in compartment and replace the exhausted battery by a new 1.5 V LR43 batter according to the polarity shown, the unit will resume working again after a few seconds.

MAXIMUN/MINIMUM TEMPERATURE & HUMIDITY RECORDING



① °C/°F SWITCH

② ON/OFF SWITCH

③ +/- SLICE SWITCH

④ BATTERY DOOR

⑤ MAGNET